



mounting hole(3) $\varnothing \frac{3}{16}$ "



3D view
code 711

soap level indicator

soap level indicator

soap level indicator